

## Lavaca Road Repair List - July 2023

PRIORITY	DRAINAGE LOCATION:	ISSUE:	RECOMMENDATION:
<b>Road Resurfacing</b>			
1	Vance St. from S. Presa to Labor St.	Poor and uneven drainage along the length of the street; abundant depressions; particularly deep depression in front of approx. 222 Vance. Totally failed pavement structure. Numerous potholes, cracks pavement surface and subgrade failures	Resurface street, repair sidewalks
2	Labor St. From Barrera to Cesar Chavez	Totally failed pavement structure. Numerous potholes, cracks and subgrade failures. This pavement failure is due to construction at 100 Labor and Victoria Commons	Repair base failures, repave street and repair sidewalks
2	Sadie St. from S. Presa to Labor	Poor pavement condition, numerous potholes, cracks, surface and subgrade failures.	Repair base failures, repave street and repair sidewalks
2	Lavaca St. 300 Block	Pooled water in abundant depressions and along sides of street	Resurface street, repair sidewalks
3	Refugio St. 300 block	Pooled water in abundant depressions and along sides of street that serve as pedX path where sidewalk is missing	Resurface street, repair sidewalks
4	San Arturo (whole street)	No drainage along sides of street, pooled water blocks pedX path where sidewalk is missing	Resurface street, add sidewalks
5	Staffel St. between Florida and Sadie	Pooling blocking the pedX path where there is no sidewalk or alternative walking path	Repair sidewalks
6	Riddle St. from S. Presa to Vance St.	Pooling along north side of street blocking the pedX path where the sidewalk is missing on both sides of the street	Repair sidewalks
7	Callaghan St. 200 & 300 blocks	Standing water mid street since resurfacing last year	Resurface street with appropriate slope to drainage
<b>Intersection Drainage</b>			
1	Claudia St. at the intersection with S. Presa	Major pooling blocking busy crosswalk for several days after rain	Grade to drain through resurfacing and / or installation and maintenance of storm drains
2	NW corner of Camargo and Indianola	Standing water and subsequent dirt/mud collection at the ADA sidewalk ramp at the NW corner of Indianola and Camargo	Grade to drain through resurfacing and / or installation and maintenance of storm drains
3	Labor St. at bustop at NW corner with Devine St.	Major pooling in street and at sidewalk ramp to this bus stop	Grade to drain through resurfacing and / or installation and maintenance of storm drains
4	S. Presa St. across from Bliss, southbound lane at border with Mission Supply parking lot	Major pooling across sidewalk and along curb at common street parking location	Grade to drain through resurfacing and / or installation and maintenance of storm drains
5	Eager St. at intersection with Devine	Standing water along curb nearing intersection	Grade to drain through resurfacing and / or installation and maintenance of storm drains
6	Leigh St. at intersections with Eager St. and Devine St. (one block apart)	Standing water along curb nearing intersection	Grade to drain through resurfacing and / or installation and maintenance of storm drains
7	Sadie St. near intersection with Riddle	Pooling along street parking	Grade to drain through resurfacing and / or installation and maintenance of storm drains